

# WEEKLY INCIDENT SUMMARY

Week ending Friday 28 February 2020

This incident summary provides information on reportable incidents and safety advice for the NSW mining industry. To report an incident to the NSW Resources Regulator: phone 1300 814 609 24 hours a day, 7 days a week.

## At a glance

High level summary of emerging trends and our recommendations to operators.

Reportable incident total	41
Summarised incident total	4

## Summarised incidents

INCIDENT TYPE	SUMMARY	RECOMMENDATIONS TO INDUSTRY
Dangerous incident IncNot0036795 Coal processing plant	<p>An operator was responding to a blockage in a feeder under a coal loading bin. The operator cleared the blockage and normal feed resumed. Shortly after, wet material flowed out of the feeder chute and hit the operator in the chest, knocking him off his feet. The operator suffered bruising.</p> <p>The plant was processing difficult material that needed the addition of water to keep it moving through the plant. This event was preceded by an upstream blockage in a sizer that was hosed out.</p>	<p>When developing the control measures to manage the risks of inundation or inrush of any substance, mines must consider:</p> <ul style="list-style-type: none"> <li>■ failure or blocking the flow channels</li> <li>■ the potential for the accumulation of water, gas or other substances, or materials that could liquefy or flow into other workings or locations.</li> </ul>



Inundation or inrush of any substance



In addition, mine operators should have a written procedure for the task of clearing a blocked chute and they should ensure workers adhere to the procedure.

Dangerous incident  
IncNot0036801  
Construction  
materials mine

A tipper truck hit overhead power lines while exiting a sand plant. The driver reported that he had lowered the body and that the body had raised again, by itself. The driver did not suffer an electric shock.

The reason the truck body was in the raised position is to be established.

Refer to:

- [Safety bulletin SB15-05 Plant contacting overhead powerlines and structures](#)



Roads or other vehicle  
operating areas



## Dangerous incident

IncNot0036820

Construction  
materials mine



Roads or other vehicle  
operating areas

A truck driver tipped a full load of material and then moved the truck forward about a metre but the tailgate did not release from the tipped mound.

The driver walked to the tailgate and put his head between the tailgate and truck body to see if something was preventing the tailgate from releasing. As he did this, the tailgate swung forward, hitting the side of the truck operator's head and causing his head to become caught between the tailgate and truck body.

The driver suffered head lacerations.

This incident is the subject of an investigation.

The NSW Resources Regulator investigated the death of a truck operator in 2016, who suffered fatal head injuries from a swinging tailgate. Two similar non-fatal incidents occurred in quick succession, leading to an awareness campaign to bring this hazard to the attention of industry. Nobody should place any part of their body between an unsecured tailgate and the truck body. This message should be reiterated to all truck operators, including contractors, on all mine sites.

Workers should be trained to recognise the hazards associated with gravity, and the controls that should be used.

Refer to:

- [Safety Alert SA20-03  
Tailgate hits worker's head](#)
- [Investigation report into  
fatality involving truck  
tailgate](#)

Serious injury  
IncNot0036829  
Underground metals  
mine



Ground or strata failure

A worker was assisting a Jumbo operator who was bolting a pillar incline. After the worker manually scaled the roof area (removed loose material), he began installing retaining caps resin capsules. He dropped a cap and bent over to pick it up. When he did this, a rock fell from beneath the mesh and hit him on the back of the head. The rock was about 50 centimetres in diameter and weighed about 20 kilograms. The worker lost consciousness briefly.

The worker's hard hat absorbed some of the impact.



Control measures to manage the risks of ground or strata failure include:

- using appropriate equipment and procedures for scaling
- the design, installation and quality of rock support and reinforcement.

Work methods must consider the risk of falling material and locations of people.

## Other publications of interest

The incidents are included for your review. The NSW Resources Regulator does not endorse the findings or recommendations of these incidents. It is your legal duty to exercise due diligence to ensure the business complies with its work health and safety obligations.

PUBLICATION	ISSUE/TOPIC
<b>International (fatal)</b>	
<b>MSHA</b>	<p><b>Coal mine fatality</b></p> <p>On 10 February 2020, a mine examiner was operating a personnel carrier down a mine intake slope. Evidence indicated the personnel carrier struck the left rib while travelling down the intake slope. The mine examiner was found unresponsive near the bottom of the slope, lying beside the personnel carrier.</p> <p><a href="#">Details</a></p>
<b>International (other, non-fatal)</b>	
<b>MinEx NZ</b>	<p><b>Plant operated without guarding</b></p> <p>A worker removed the rear guarding on a feeder to remove rocks. After removing the rocks, the worker failed to replace the guarding.</p> <p><a href="#">Details</a></p>
<b>National (fatal)</b>	
<b>WorkSafe VIC (in MinEx NZ)</b>	<p><b>Hot works cause quarry fire</b></p> <p>WorkSafe Victoria recently issued a safety alert about the risks associated with hot works, after a hopper liner and screen caught fire at a quarry.</p> <p><a href="#">Details</a></p>

**Note:** While the majority of incidents are reported and recorded within a week of the event, some are notified outside this time period. The incidents in this report therefore have not necessarily occurred in a one-week period. All newly recorded incidents, whatever the incident date, are reviewed by the Chief Inspector and senior staff each week. For more comprehensive statistical data refer to our annual performance measures reports.

© State of New South Wales through the NSW Department of Planning, Industry and Environment 2020

This publication is copyright. You may download, display, print and reproduce this material in an unaltered form only (retaining this notice) for your personal use or for non-commercial use within your organisation. To copy, adapt, publish, distribute or commercialise any of this publication you will need to seek permission from the NSW Department of Planning and Environment.

Disclaimer: The information contained in this publication is based on knowledge and understanding at the time of writing (March 2020). However, because of advances in knowledge, users are reminded of the need to ensure that information upon which they rely is up to date and to check currency of the information with the appropriate officer of the NSW Department of Planning and Environment or the user's independent advisor.

**DOCUMENT CONTROL**

<b>CM9 reference</b>	DOC20/176176
<b>Mine safety reference</b>	ISR20-09
<b>Date published</b>	6 March 2020
<b>Approved by</b>	Chief Inspector Office of the Chief Inspector