

Fact sheet

Principal hazard – ground or strata failure (underground)

October 2024



The Resources Regulator has developed a broad-brush risk assessment and a program of bowties to review principal hazards and control plan topics.

The bowtie program identified the material unwanted events (MUE) and critical controls to prevent serious injury or death of mine workers.

The bowtie for the principal hazard of ground or strata failure (underground) identified one MUE and the critical controls for assessment programs. This fact sheet provides information related to the assessment program focussing on the MUE – uncontrolled movement of ground (underground).

Principal hazard — ground or strata failure (underground)

MUE — uncontrolled movement of ground (underground)

MUE critical controls

The Regulator's assessment program will focus on the following critical controls to prevent an uncontrolled movement of ground (underground):

- the mine (layout, sequence, method and support) is designed to geotechnical, strata and hydrogeological conditions
- use of ground support (designed and executed to maintain stable ground)
- engineered operator protection devices
- drill and blast management
- workers are restricted/removed from high-risk areas.

Considerations

Mine operators should consider the material unwanted events above as a minimum and ensure that the review of critical controls to prevent serious injury or death is included within the site principal hazard management plans and associated documentation.

Other relevant safety alerts, safety bulletins and information resources published by the Resources Regulator:



Fact sheet – Principal hazard – ground or strata failure (underground)

Date published	Reference	Title
July 2024	Investigation Information Release IIR 24-05	Dangerous incident at Clarence Colliery – roof fall
June 2023	Safety Bulletin SB23-06	Rockfall injuries to workers increase in underground mines
February 2023	Consolidated Report	<u>Ground or strata failure - underground coal mines -</u> secondary extraction
July 2022	Investigation Information Release IIR 22-03	<u>Worker's leg fractured during strata support work in a</u> coal mine drift
January 2022	Safety Bulletin SB22-02	Strata failures increase in underground coal mines across the state
December 2021	Investigation Information Release IIR 21-12	Roof ply rock falls on two workers during pillar extraction
October 2021	Safety Bulletin SB21-07	Polyurethane Resin selection
August 2021	YouTube video	Centennial Strata Incident Animation 13/08/2021
December 2020	Consolidated Report	Managing ground or strata failure risks in underground coal mines
February 2020	Safety Alert SA20-01	<u>Roof fall buries a continuous miner – miners take evasive</u> action to prevent injury
November 2019	Safety Bulletin SB19-15	Rapid face bolters incidents
July 2018	Investigation Information Release IIR 18-05	<u>Serious injury</u>
February 2015	Code of Practice	Strata control in underground coal mines
August 1992	MDG 1005 Part 1	Manual on pillar extraction in NSW underground coal mines

References	
Program type	PH-0403
Principal hazard	0403 Ground or strata failure (underground)
MUE number	MUE03

Fact sheet – Principal hazard – ground or strata failure (underground)

© State of New South Wales through the Department of Primary Industries and Regional Development 2024. You may copy, distribute, display, download and otherwise freely deal with this publication for any purpose, provided that you attribute the Department of Primary Industries and Regional Development as the owner. However, you must obtain permission if you wish to charge others for access to the publication (other than at cost); include the publication in advertising or a product for sale; modify the publication; or republish the publication on a website. You may freely link to the publication on a departmental website.

Disclaimer: The information contained in this publication is based on knowledge and understanding at the time of writing (September 2024) and may not be accurate, current or complete. The State of New South Wales (including the Department of Primary Industries and Regional Development), the author and the publisher take no responsibility, and will accept no liability, for the accuracy, currency, reliability or correctness of any information included in the document (including material provided by third parties). Readers should make their own inquiries and rely on their own advice when making decisions related to material contained in this publication.