

**NSW
Resources
Regulator**

Investigation report

Fatality on surface of underground coal mine at Wongawilli
Colliery on 1 June 2017



Document control

Published by NSW Department of Planning and Environment, NSW Resources Regulator

Title: Investigation report – Fatality on surface of underground coal mine at Wongawilli Colliery on 1 June 2017

First published: August 2018

Authorised by: Director Major Investigations Unit

CM9 reference: DOC18/475221

© State of New South Wales through the NSW Department of Planning and Environment 2018.

This publication is copyright. You may download, display, print and reproduce this material in an unaltered form only (retaining this notice) for your personal use or for non-commercial use within your organisation. To copy, adapt, publish, distribute or commercialise any of this publication you will need to seek permission from the NSW Department of Planning and Environment.

Disclaimer: The information contained in this publication is based on knowledge and understanding at the time of writing (August 2018). However, because of advances in knowledge, users are reminded of the need to ensure that information upon which they rely is up to date and to check currency of the information with the appropriate officer of the NSW Department of Planning and Environment or the user's independent advisor.

Overview

On 1 June 2017, a worker, aged 48, and contractors were conducting soil sampling and clean-up works around the Wongawilli No.1 ventilation shaft as part of the rehabilitation of the disused mine surface infrastructure.

The worker told contractors he felt unwell and left the work site alone in a light vehicle to seek medical attention. The worker was later found by the contractors lying on the ground near the light vehicle on the access road about 1.5 kilometres from the ventilation shaft.

The NSW Ambulance Service responded to the emergency call and determined that the worker was deceased.

Investigation outcome

The NSW Resources Regulator has conducted a detailed investigation into the circumstances of the worker's death. The regulator does not consider the worker's death to be workplace-related.

The NSW Coroner has dispensed with holding an inquest.

Further information

Related publications:

- [IIR17-07 Fatality on surface of underground coal mine](#)
- [Health management overview](#)
- [Understanding health monitoring](#)

About this report

The Resources Regulator has issued this information to draw attention to the occurrence of a death in the mining industry. The investigation has concluded and no further information will be published.

Go to resourcesandgeoscience.nsw.gov.au/regulation/safety-and-health to:

- learn more about our major investigations
- view our publications on other major investigations
- find your local mine safety office, where you can contact our team of mine safety inspectors.

Office use only

CM9 reference	DOC18/475221
Published	8 August 2018
Authorised by	Steve Orr, Acting Director Major Investigations

© State of New South Wales through the NSW Department of Planning and Environment 2018.

This publication is copyright. You may download, display, print and reproduce this material in an unaltered form only (retaining this notice) for your personal use or for non-commercial use within your organisation. To copy, adapt, publish, distribute or commercialise any of this publication you will need to seek permission from the NSW Department of Planning and Environment.

Disclaimer: The information contained in this publication is based on knowledge and understanding at the time of writing (August 2018). However, because of advances in knowledge, users are reminded of the need to ensure that information upon which they rely is up to date and to check currency of the information with the appropriate officer of the NSW Department of Planning and Environment or the user's independent advisor.